





Torque sensors




Send us your shaft - We turn it into a torque sensor!








Realization examples





Sensor square version





- Calibration up to 50 000 Nm torque (> request us)
- Conversion of almost all shafts possible
- Depending on shaft material, small linearity deviation of ≤ 1%
- Analog output signals DMS mV/V (standard), ± 0 10V, 0/4 20mA